

**APPENDIX - VIII**

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION  
CERTIFICATE.**

No. 1232

Date : 30.03.2022

It is certified that an inspection team headed by P.K. Gogade Executive Engineer (Name of Officers with designation) from Public Health Engg. Div. Ratlam (Name of Department/Office) inspected the Maruti Academy Satrunda, Mhow-Neemuch Road, Ratlam (Name & Address of the School) on and found that the Maruti Academy Satrunda, Ratlam. (Name of school) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/State/U.T Govt.

The above valid for a period of Year-2022-23

Signature with Seal [Signature]  
Executive Engineer  
PH. Engg. Division, Ratlam

Name : P.K. Gogade

Designation : Executive Engineer

To

Principal  
Maruti Academy Satrunda,  
Ratlam.  
(Name & Address of the Institution)

[Signature]  
President/Secretary/Treasurer  
Maruti Academy, Satrunda  
Affiliated to C.B.S.E., Dehli  
Affi. No. 1030340  
Mhow-Neemuch Raod  
Ratlam (M.P.)

[Signature]  
Principal  
Maruti Academy, Satrunda  
Affiliated to C.B.S.E., Dehli  
Affi. No. 1030340  
Mhow-Neemuch Raod  
Ratlam (M.P.)